

Air Conditioning Inspection Certificate

Site Details:

Equipment Owner's Organisation		William Hill PLC			
Equipment Owner's / Manager Name		Manager	Telephone	+44 (0)20 8918 3600	
Equipment Owner's Address		Greenside House, 50 Station Road, Wood Green, London, N22 7TP			
Site Address (where inspection was carried out)		William Hill Bookmakers, 274-276 Laird Street, BIRKENHEAD, CH41 8EW			
City	BIRKENHEAD	Post code	CH41 8EW	RRN	0990-2021-5760-7700-5603
Related RRN	0750-0056-1759-0722-9002	UPRN	505790710000	AC Inspection Level	Level 3

Report Information:

Inspection Date	2016-02-23	Next Inspection Date	2021-02-23	Issue Date	2016-03-08
-----------------	------------	----------------------	------------	------------	------------

Assessor Details:

Assessor Name	Stephen Edwards	Assessor ID	STER001047
Employer/Trading Name	ACI Reports Ltd		
Employer/Trading Address	Suite A9, Allied Business Centre, Potter Place, Skelmersdale, WN8 9PW		
Accreditation Scheme Name	Sterling Accreditation Limited		
Website Address			
Related Party Disclosure	Not related to the owner/occupier or person who has technical control of the system or subcontractor.		
Assessment Software Used	Sterling Accreditation, Sterling e-Volve, v1.2		

F-Gas Compliant Date/ Not Applicable	Not Provided	Total Effective Rated Output (kW)	17	System Sampling?	No
Treated Floor Area (m²)	103	Air Conditioning Sub Systems Metered?	No	Total Estimated Refrigerant Charge (kg)	7

The following sub systems were inspected in accordance with DCLG guidance to produce this air conditioning report

Sub System ID	Sub System Description	Refrigerant Type(s)	Age(s) of Main Components
VOL001/SYS001 Customer Standing Area	One Mitsubishi split system PUHZ-RP71VHA4 condenser serving one Mitsubishi ceiling cassette.	R410A	2010
VOL001/SYS002 Customer Seating Area	One Mitsubishi split system PUHZ-RP71VHA4 condenser serving one Mitsubishi ceiling cassette.	R410A	2010
VOL001/SYS003 Counter Area	One Mitsubishi split system SUZ-KA25VA2 condenser serving one Mitsubishi ceiling cassette.	R410A	2010

I certify that the above sub systems have been inspected in accordance with the approved methodology

Air Conditioning Inspection Certificate

About this document and the data in it

This document has been produced following an energy assessment undertaken by a qualified Energy Assessor, accredited by Sterling Accreditation Limited. You can obtain contact details of the Accreditation Scheme at www.sterlingaccreditation.com.

A copy of this certificate has been lodged on a national register as a requirement under the Energy Performance of Buildings Regulations 2012 as amended. It will be made available via the online search function at www.ndepcregister.com. The certificate (including the building address) and other data about the building collected during the energy assessment may be made publicly available at www.opendatacommunities.org.

This certificate and other data about the building may be shared with other bodies (including government departments and enforcement agencies) for research, statistical and enforcement purposes. Any personal data it contains will be processed in accordance with the General Data Protection Regulation and all applicable laws and regulations relating to the processing of personal data and privacy. For further information about this and how data about the property are used, please visit www.ndepcregister.com. To opt out of having information about your building made publicly available, please visit www.ndepcregister.com/optout.

There is more information in the guidance document *Air-conditioning inspections for buildings* available on the Government website at: www.gov.uk/government/collections/energy-performance-certificates. It explains the content and use of this document, advises on how to identify the authenticity of a certificate and how to make a complaint.